# State of New Mexico
## Energy, Minerals and Natural Resources Department

**Susana Martinez**
Governor

**David Martin**
Cabinet Secretary

**Tony Delfin**
Deputy Cabinet Secretary

**David Catanach, Director**
Oil Conservation Division

**\*Response Required - Deadline Enclosed\***

*Underground Injection Control Program*

*"Protecting Our Underground Sources of Drinking Water"*

**HOBBS OCD**

**AUG 0 3 2016**

**RECEIVED**

*03-Aug-16*

CHEVRON U S A INC
ATTN:PERMITTING TEAM   6301 DEAUVILLE BLVD.
MIDLAND  TX  79706-

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE**
**Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

### MECHANICAL INTEGRITY TEST DETAIL SECTION

**VACUUM GLORIETA WEST UNIT No.113**                                    30-025-21107-00-00

Approved TA Oil (Producing)                                              C-1-18S-34E

| | | | |
|---|---|---|---|
| **Test Date:** 8/3/2016 | **Permitted Injection PSI:** | **Actual PSI:** | |
| **Test Reason:** TA Status Test | **Test Result:** F | **Repair Due:** 11/6/2016 | |
| **Test Type:** Std. Annulus Pres. Test | **FAIL TYPE:** Other Internal Failure | **FAIL CAUSE:** | |

**Comments on MIT:**   MIT-FAILURE. RULE: 19.15.25.14

**EMNRD**
**OIL CONSERVATION DIVISION**
**1625 N FRENCH DRIVE**
**HOBBS NM 88240**

CHEVRON USA INC
ATTN: SANDY SEDMAN-DANIEL 1400 SMITH
HOUSTON TX 77002