Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

WELL API NO.
30-025-05575

5. Indicate Type of Lease
STATE **X**   FEE

6. State Oil & Gas Lease No.
005892

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well   Gas Well **X**   Other   Injection Well

2. Name of Operator
LEWIS B. BURLESON, INC.

3. Address of Operator
P.O. Box 2479, Midland, TX 79702

7. Lease Name or Unit Agreement Name

SHELL STATE

8. Well Number   1

9. OGRID Number
013300

10. Pool name or Wildcat
EUMONT (YTS-74-QN) GAS

4. Well Location
Unit Letter____E____: 1980 feet from the ____NORTH____ line and ____660ᵈ____ feet from the _West____ line
Section 7   Township 19S   Range 37E   NMPM   County **LEA**

11. Elevation *(Show whether DR, RKB, RT, GR, etc.)*
3728' GR

Pit or Below-grade Tank Application **X** or Closure ☐

Pit type_____ Depth to Groundwater__58'____ Distance from nearest fresh water well___1000' Distance from nearest surface water_____

Pit Liner Thickness: mil   Below-Grade Tank: Volume_____ bbls; Construction Material : Above Ground Pit

---

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON		
TEMPORARILY ABANDON ☐	CHANGE PLANS	☐	
PULL OR ALTER CASING ☐	MULTIPLE COMPL	☐	

OTHER: ☐

SUBSEQUENT REPORT OF:

|			
REMEDIAL WORK	☐	ALTERING CASING	☐
COMMENCE DRILLING OPNS.	☐	P AND A	**X**
CASING/CEMENT JOB	☐		

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-14-06 Tag CIBP @3,284'.
6-15-06 Circulate hole with mud. Spot 25 sx. cmt. on CIBP @3,284'. Perf. 4 holes @1,400'. Set pkr. @1,065'. Sqz. 35 sx. cmt. Tag plug @1,255'. Perf. 4 holes @424'. Sqz. 12 sx. cmt. down 5 ½" to surface out of 8 5/8". Leave 5 ½" full of cement.
6-16-06 Install Dryhole Marker.

Approved as to plugging of the Well Bore.
Liability under bond is retained until surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. **I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.**

SIGNATURE _____ TITLE **P & A SUPERVISOR**   DATE: **6-22-06**

Type or print name **RANDALL MINEAR**   Telephone No. 432-530-0907

For State Use Only

APPROVED BY: _____ TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER   DATE **JUL 0 7 2006**
Conditions of Approval (if any):