Form 3160-5
(April 2004)

RECEIVED
OCD-IN???S 2009
HOBBSOCD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- *Other instructions on reverse side.*

5 Lease Serial No NM.052	
6 If Indian, Allottee or Tribe Name	
7 If Unit or CA/Agreement, Name and/or No	

1 Type of Well
☐ Oil Well ☐ ☐ ☐ Gas Well ☐☐ ☑ Other **Inj**

8 Well Name and No
Mescalero Ridge Unit 35 #8

2 Name of Operator **Merit Energy Company**

9 API Well No
30-025-20695

3a Address
13727 Noel Rd. Suite 500 Dallas, Texas 75240

3b- Phone No *(include area code)*
972-628-1569

10 Field and Pool, or Exploratory Area
Pearl Queen

4 Location of Well *(Footage, Sec , T., R., M., or Survey Description)*
1980' FSL & 1980' FWL Sec. 35-T19S-R34E

11 County or Parish, State
Lea Co., New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☑ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☑ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

MIRU PU. ND WH. NU BOPE. Unseat injection pkr. POOH w/pkr. & tbg. standing back. PU. RIH w/Baker fullbore pkr. Set +/- 50' above perforations. Test csg. PU. RIH w/injection pkr. on 2-3/8" injection tbg. string testing in. Replace any bad jts. of tbg. Set injection pkr. +/- 50' above perforations. ND BOPE. NU WH. RDMO PU. Perform MIT.

✳ Reminder — Since this is an Unit well, operator is to submit NOI PRIOR to work being done.

14 I hereby certify that the foregoing is true and correct
Name *(Printed/Typed)*

Signature

Title **REGULATORY MANAGER**

Date **10/15/09**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 11/16/09
Office

NOV 10 2009
/s/ Dustin Winkler

NOV 18 2009

(Instructions on page 2)