NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

APR II 1 34 PM '59

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State [X]   Fee [ ]

5. State Oil & Gas Lease No.
1147-12-66

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)

1.
OIL WELL [X]   GAS WELL [ ]   OTHER-

2. Name of Operator
American Trading and Production Corporation

3. Address of Operator
P. O. Drawer 992, Midland, Texas   79701

4. Location of Well

UNIT LETTER _____ . 2310 FEET FROM THE __North__ LINE AND __990__ FEET FROM

THE __West__ LINE, SECTION __19__ TOWNSHIP __9-S__ RANGE __33-E__ NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
New Mexico "19" State

9. Well No.
1

10. Field and Pool, or Wildcat
Flying M, South

15. Elevation (Show whether DF, RT, GR, etc.)
4395 DF; 4384 GR

12. County
Lea

16.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [ ]

TEMPORARILY ABANDON [ ]

PULL OR ALTER CASING [ ]

PLUG AND ABANDON [X]

CHANGE PLANS [ ]

OTHER _____ [ ]

SUBSEQUENT REPORT OF:

REMEDIAL WORK [ ]

COMMENCE DRILLING OPNS. [ ]

CASING TEST AND CEMENT JOB [ ]

OTHER _____

ALTERING CASING [ ]

PLUG AND ABANDONMENT [ ]

[ ]

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

American Trading and Production Corporation proposes to permanently abandon the above well as follows during the month of April, 1969: Circulate 9.5# brine gel fluid from 9150' to surface and pump cement plugs as listed.

```
        25 sacks from 9050' - 9150' over 5 1/2" casing perforations.
        25 sacks from 6150' - 6250' over 5 1/2" stub, open hole.
        25 sacks from 5000' - 5100' over Glorieta formation, open hole.
        25 sacks from 3600' - 3700' over 8 5/8" surface shoe joint and open hole.
        10 sacks from    0' -   50' inside 8 5/8" surface casing
         1 - 4" well marker and 8 5/8" screw cap.
```

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____   TITLE **District Engineer**   DATE **April 6, 1969**

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY: