NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease: State [X] Fee [ ]

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT –" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL [ ] GAS WELL [ ] OTHER- Dry Hole

7. Unit Agreement Name

2. Name of Operator: Apexco, Inc.

8. Farm or Lease Name: State #7

3. Address of Operator: Box 2299, Tulsa, Oklahoma 74101

9. Well No.: 1

4. Location of Well: UNIT LETTER B, 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 9S RANGE 33E NMPM.

10. Field and Pool, or Wildcat: Wildcat

15. Elevation *(Show whether DF, RT, GR, etc.)*: GR 4392'

12. County: Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: Amended

- PERFORM REMEDIAL WORK [ ]
- TEMPORARILY ABANDON [ ]
- PULL OR ALTER CASING [ ]
- PLUG AND ABANDON [X]
- CHANGE PLANS [ ]
- OTHER [ ]

SUBSEQUENT REPORT OF:

- REMEDIAL WORK [ ]
- COMMENCE DRILLING OPNS. [ ]
- CASING TEST AND CEMENT JOB [ ]
- ALTERING CASING [ ]
- PLUG AND ABANDONMENT [ ]
- OTHER [ ]

17. Describe Proposed or Completed Operations *(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)* SEE RULE 1103.

This well was drilled to a total depth (4515') with no show of Oil or gas. We plan to plug and abandon the well using the following procedure.

1. Fill the hole with heavy mud laden fluid
2. Set 100 foot cement plug 4333' - 4487'
3. Set 100 foot cement plug on top of 5½" stub
4. Set 475 foot cement plug 2,000' - 2475(in the salt section if above 5½" stub)
5. Set 100 foot cement plug in and out of the 8 5/8" surface casing (337' - 437')
6. Set 10 sacks cement plug in the top of the surface casing
7. Install regulation dry hole marker.
8. Fill the pits, level the location, & clear location of junk

Notify in advance 24 hours prior to setting plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lapt D. Somers TITLE Regional Prod. Manager DATE 11-13-73

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: