Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONS. COMMIS.
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-044216

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER	7. UNIT AGREEMENT NAME Bluitt San Andres Unit

2. NAME OF OPERATOR
MURPHY OPERATING CORPORATION

8. FARM OR LEASE NAME
Bluitt San Andres Unit Sec. 13

3. ADDRESS OF OPERATOR
P. O. Drawer 2648, Roswell, NM 88202-2648

9. WELL NO.
11

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit Ltr. K, 1980' FSL & 1980' FWL, Sec. 13, T8S, R37E

10. FIELD AND POOL, OR WILDCAT
Bluitt San Andres Assoc.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 13, T8S, R37E

14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3997.5' GR	12. COUNTY OR PARISH Roosevelt	13. STATE New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) _____	
(Other) _____		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

RU PU. TOH w/4708.91' (150 jts.) 2-3/8" 4.7# J-55 tubing. New PBTD 4721.52'. TIH w/AD-1 packer. Set at 4520.71'. Acidize w/2,400 gals. 15% Ne-WS48 acid. Drop 18 ball sealers. Well balled off. Flush w/20 bbls. 2% KCl. ISIP - well on vacuum. Maximum rate - 3.8 BPM, average rate - 3.5 BPM. Maximum pressure - 3,200 psi, average pressure - 0 psi. TOH w/ packer. TIH w/production string. Return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED *Melinda K. Hickman*
Melinda K. Hickman

TITLE Production Supervisor   DATE 9-26-88

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD
PETER W. CHESTER
DATE

OCT 19 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA