Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP~~~ TE*
(Other Instruction
verse side) re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 060811

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.

OIL WELL ☐   GAS WELL ☐   OTHER   Water Injection

7. UNIT AGREEMENT NAME

D.Q.S.U.

2. NAME OF OPERATOR

Guest & Wolfson ~~Oil Company~~

8. FARM OR LEASE NAME

Tract 1

3. ADDRESS OF OPERATOR

1011 Hamilton Building, Wichita Falls, Texas 76301

9. WELL NO.

5

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 990' FEL

10. FIELD AND POOL, OR WILDCAT

Caprock Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

15-T14S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4417' GR

12. COUNTY OR PARISH   13. STATE

Chaves   N. M.

16.   Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	X
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Proposal to plug and abandon above well in following manner:

1. Set CIBP or 25 Sx plug to cover existing perforations.
2. Load hole w/mud-laden fluids.
3. Shoot & recover production casing.
4. Spot 100' plug at casing stub.
5. Spot 100' plug in and out of 12-3/4 casing, set @ 246'.
6. Spot 10 Sx top hole plug & erect 4" regulation marker.

RECEIVED

MAR [illegible] 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED _S. Sacker_   TITLE ___Agent___   DATE __3/26/74__

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ADDED

APR 3 - 1974

H. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side