Form 9–331
(May 1963)

UN ED STATES
DEPARTMENT OF THE INTERIOR
☐ GEOLOGICAL SURVEY

SUBMIT IN TRIPLICA
(Other instructions on verse side)

Form approved.
Budget Bureau No. 42–R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM 0354478

6. IF INDIAN, ALLOTTED OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.
OIL WELL ☐   GAS WELL ☐   OTHER   Wildcat

2. NAME OF OPERATOR
Grover, MacCurdy and Hoffacker

3. ADDRESS OF OPERATOR
306 Midland Nat'l Bank Bldg., Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL and 660' FWL of Section 19

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Shell-Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 19, T9S, R30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4039.9 Gr.

12. COUNTY OR PARISH
Chaves

13. STATE
New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	
SHOOT OR ACIDIZE ☐	ABANDON* ☒	
REPAIR WELL ☐	CHANGE PLANS ☐	
(Other)		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐	
FRACTURE TREATMENT ☐	ALTERING CASING ☐	
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐	
(Other) _____		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Notice of intention to plug and abandon well on March 29, 1968 as follows:

100' cement plug from 3265' to TD 3365'.
100' plug - 50' plug in and out of top of 4 1/2" casing @ approximately 2350'.
100' plug - 50' above and below T/Yates @ 1395'.
100' plug - 50' in and out of 8 5/8" casing @ 345'.
20' plug in top of 8 5/8" casing.
No 8 5/8" casing to be pulled.
4 1/2" pipe marker to be cemented at surface in top of 8 5/8" casing.

18. I hereby certify that the foregoing is true and correct

SIGNED _____   TITLE   Partner   DATE   4-8-68

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:
APPROVED

APR   1968

J. W. SUTHERLAND
DISTRICT ENGINEER

*See Instructions on Reverse Side