2-10-83   Spot 6 BBls. 15% NEHCL to 10354/Wash perfs 2½ hrs w/1000# back press
moving acid ¼BBl every 15 min/Raise & set PKR 10137 (1000#)/Dresser Titan
attemp break perfs 10315-10350 w/Max TP 4200. Did not break/lower PKR to
10360 Rev out acid/respot 6 BBLs. 15% NEHCL to PKR at 10360/Wash perfs 2hrs
w/1200# back pressure moving acid ¼ bbl every 15 min/Raise & set PKR 10137
Open-by-pass Rev 3bbl in tbg close by pass (trap 1000# on csg) Dresser
Titan attmep break perfs w/Max TP 600#. Did not break/SDFN w/6000# left on tbg.

2-11   Pressure tbg to 6000# w/no bleedoff/Lower PKR to 10360 Rev out acid/
respot 4 BBl 15% NEHCL 10360-10172/POH w/PKR & 2-7/8 tbg/CRC reperf Wolfcamp
perfs 10315-14, 10335-41, 10346-50 2 JSPF (41 holes) w/4" csg gun 23 gram
(.48 EH) by Schlum Sonic Log (11-8-69). RIH w/5½ RDG on 2-7/8 tbg to 5240.

2-12   Finish 1H w/5½ RDB on 2-7/8 tbg to 10137/set PKR (1200#) Dresser Titan
attemp break perfs 10315-10350 w/Max TP 6200# would not break/lower PKR to
10360/Rev out acid/spot 6 bbls 15% NEHCL to 10360/ wash perfs 2½ hrs holding
1200# back pressure moving acid ¼ bb; everu 15 min/Raise & set PKR 10137 (1200#)
attemp break perfs w/Max TP 6200E. Did not break/lower PKR to 10360. Rev out
acid circ hole clean/PU to 10137.

2-15   POH w/RDG on 2-7/8 tbg/RIH w/ret tool on 2-7/8 tbg tag & wash fill 10364-10369/
latch RBP @ 10369 attemp rise RBP 1½ hrs w/no success.

2-16   Worked RBP 1 hr. No movement/unlatch RPB load hole w/200 BBls/circ clean/
latch RBP let equal. 1 hr/worked RBP 1½ hr could not release/unlatch from RBP/
POH w/ret tool & 2-7/8 tbg/RIH w/ret tool bumper sub, Jars 6-3½ DC acceleretor sub,
on 2-7/8 tbg to 2890.

2-17   Cont 1 hr w/fishing ass'y'/Latch RBP @ 10369/Worked and jar on RBP for 2½
hrs w/15,000 over Max Jar wt/Jar ret tool loose from RBP unable to relatch/POH
LD DC's Jars bumper sub & ret tool/RIH w/2-7/8 tbg to 5270.

2-18   Finish 1 hr w/2-7/8 tbg to 10351/LD rods from Derrick.