TAPE
C.S.
D OFFICE
RATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Effective 1-1-65

5a. Indicate Type of Lease
State [ ] Fee [ ]

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

7. Unit Agreement Name

OIL WELL [ ] GAS WELL [ ] OTHER-

8. Farm or Lease Name
Grimes

Name of Operator
Shell Oil Company (Equivalon Oil Co.)

9. Well No.
2

Address of Operator
P.O. Box 991 Houston, TX 77001

10. Field and Pool, or Wildcat
Hobbs(G/SA)

Location of Well
UNIT LETTER H 990 FEET FROM THE east LINE AND 2310 FEET FROM

THE north LINE, SECTION 29 TOWNSHIP 18S RANGE 38E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3650' GL

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ]
TEMPORARILY ABANDON [ ]
PULL OR ALTER CASING [ ] AMENDED CHANGE PLANS [ ]
OTHER RE-ENTER AND REPLUG [ ]

SUBSEQUENT REPORT OF:

REMEDIAL WORK [ ] ALTERING CASING [ ]
COMMENCE DRILLING OPNS. [ ] PLUG AND ABANDONMENT [ ]
CASING TEST AND CEMENT JOB [ ]
OTHER [ ]

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Dig out cellar. Remove marker. Rig up PU and reverse circulator.
2. Drill out cement in 15 1/2" csg. Clean out to 3930'.
3. Spot 100' Class "C" cmt plugs @3930'-3830'; 3400'-3300'; 2080'-1980'; 1250'-1150'.
4. Spot Class "C" cmt plug from 400 ft-200ft. Spot 10 ft cmt plug at surface.
5. Weld plate over 15 1/2" csg. Install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A.J. Fore TITLE Supervisor Regulatory & Permits DATE January 30, 1981

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: