Attachment for C-105

Pearl Area Wildcat
Hooper 1

Perforated 5 1/2" casing 8450'-8510' with 4 jet shots per foot.

Washed casing perforations 8450'-8510' with 500 gallons MCA.

Treated thru casing perforations 8450'-8510' with 500 gallons MA and 1000 gallons 15% LST non-swelling, non-emulsion acid.

Treated thru casing perforations 8450'-8510' with 5,000 gallons (CP) Type J acid.

Perforated 5 1/2" casing with 4 jet shots per foot from 8198'-8272'.

Set retrievable Bridge plug @ 8330'.

Washed casing perforations 8198'-8272' with 500 gallons MCA.
Treated thru casing perforations 8198'-8272' with 500 gallons MCA and 1000 Gallons 15% LST acid.

Treated thru casing perforations 8198'-8272' with 5000 gallons 15% Type J acid. (CP).

Treated thru casing perforations 8198'-8272' with 2000 gallons Channel acid followed by 10,000 gallons 15% LST non-swelling, non-emulsifying acid.

Treated thru casing perforations 8198'-8272' with 10,000 gallons Dowell acid Petrofrac containing 1 pound sand per gallon.

On OPT in 24 hours flowed 279 BO, cut 3% BS&W, thru 1" choke.