Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-26569

5. Indicate Type of Lease
STATE ☒   FEE ☐

6. State Oil & Gas Lease No.
B-2388

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
EAST VACUUM GB/SA UNIT
TRACT 2059

1. Type of Well:
OIL WELL ☐   GAS WELL ☐   OTHER **WATER INJECTION**

2. Name of Operator
Phillips Petroleum Company

8. Well No.
003

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

9. Pool name or Wildcat
VACUUM GB/SA

4. Well Location
Unit Letter **F** : **2630** Feet From The **NORTH** Line and **1330** Feet From The **WEST** Line

Section **20**   Township **17 S**   Range **35 E**   NMPM   **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3975.5' GR

11.   **Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐   PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐   CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: _____ ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐   ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐   PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: _____ ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. NU BOP. SET 4-1/2" CIBP AT 4509'. CIRCULATE CSG W/9.5 MUD-LADEN FLUID.
2. SPOT PLUG NO. 1 (35 SX CMT) 4509'-4140'. COVERS THE GB/SA.
3. SPOT PLUG NO. 2 (25 SX CMT) 3000'-2900'. COVERS THE YATES.
4. SPOT PLUG NO. 3 (25 SX CMT) 1800'-1700'. COVERS THE SALT TOP AND SURFACE SHOE.
5. SPOT PLUG NO. 4 (30 SX CMT) 400'-3'.
6. CUT OFF CASING 3' BELOW GROUND LEVEL. INSTALL MONUMENT MARKER. PERFORM RECLAMATION WORK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____   TITLE **SUPERVISOR, REG. AFFAIRS**   DATE **3/3/95**

TYPE OR PRINT NAME **L. M. SANDERS**   TELEPHONE NO. **915/368-1488**

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

MAR 07 1995

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY: