STATE OF NEW MEXICO
NERGY AND MINERALS DEPARTMENT

| NO. OF COPIES RECEIVED | | |
|---|---|---|
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

# OIL CONSERVATION DIVISION
### P. O. BOX 2088
## SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State [XX]   Fee [ ]

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL [X]    GAS WELL [ ]    OTHER:

7. Unit Agreement Name

Name of Operator
Chevron U.S.A. Inc.

8. Farm or Lease Name
Lea "ED" State (NCT-A)

Address of Operator
P.O. Box 670, Hobbs, NM 88240

9. Well No.
4

Location of Well

UNIT LETTER __K__ , __2230__ FEET FROM THE __South__ LINE AND __2200__ FEET FROM

THE __West__ LINE, SECTION __16__ TOWNSHIP __19S__ RANGE __34E__ NMPM.

10. Field and Pool, or Wildcat
Quail Ridge/Bone Spring

15. Elevation (Show whether DF, RT, GR, etc.)
3774'

12. County
Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

RFORM REMEDIAL WORK [ ]
MPORARILY ABANDON [ ]
LL OR ALTER CASING [ ]
PLUG AND ABANDON [ ]
CHANGE PLANS [ ]
OTHER wtr shut off, sqz perfs, acdz [X]

SUBSEQUENT REPORT OF:

REMEDIAL WORK [ ]
COMMENCE DRILLING OPNS. [ ]
CASING TEST AND CEMENT JOB [ ]
OTHER _____
ALTERING CASING [ ]
PLUG AND ABANDONMENT [ ]

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to water shut off, scale convert, and acdz the subject well as follows: POOH w/production equip, RIH to PBTD, 10,155. Set RBP at 10,075 ± isolate perfs 10,032 -- 10,037. Swab test perfs, based on results, the interval may be squeezed. If squeeze is necessary, set CIBP at 10,060±. Test squeeze, drill out CIBP at 10,060 and clean out to PBTD, acidize perfs, swab. Chem squeeze perfs, Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

_M. E. Abney_    TITLE Staff Drilling Engineer    DATE October 6, 1987

ORIGINAL SIGNED BY JERRY SEXTON
OVED BY    DISTRICT I SUPERVISOR    TITLE _____    DATE _____

NDITIONS OF APPROVAL, IF ANY: