Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-025-31373

5. Indicate Type of Lease

STATE ☒   FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
   Oil Well ☒   Gas Well ☐   Other

2. Name of Operator
   Santa Fe Snyder Corporation

3. Address of Operator
   550 W. Texas, Suite 1330, Midland, TX 79701

7. Lease Name or Unit Agreement Name:

Maggie 16 State

8. Well No.
   1

9. Pool name or Wildcat
   Young (Queen)

4. Well Location

Unit Letter ____I____ : __2310'__ feet from the __South__ line and __990'__ feet from the __East__ line

Section __16__   Township __18 S__ Range __32E__ NMPM   County __Lea__

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3785'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐   PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐   CHANGE PLANS ☐

PULL OR ALTER CASING ☐   MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒   ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐   PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

3/23/00 Road to location dig out 8 5/8" csg, set anchors
3/24/00 MIRU GIH W 6 1/4" mill, cut over dry hole marker, PU. GIH W/ 7 7/8" bit drill out cmt @ 60'.
Tag cmt @ 225' drill out to 407'. Tag cmt @ 2800' drill out to 2854', POOH. GIH W/ 7 1/2" globe mill
tag @ 2854', mill to 2865', POOH. GIH W/ 7 1/2"amill tag @ 2865', mill ato 2885', POOH. GIH W/ 7 7/8"
bit tag fill @ 2911', drl cmt to 2993'. Tag top of 5 1/2" cag @ 2997' circ hole clean, POOH. GIH W/ 4
3/4" bit drill 100' cmt POOH. GIH tag TD @ 3200'. POOH lay down tbg, shutdown wait for cement equipment
to P&A the well.
4-11-00 GIH W/ tbg to 3200', pmp 25 sx Class 'C; + 2% CCL, POOH. Wait 4 hrs, tag fill @ 3140'. GIH spot
25 sx Class 'C' + 2% CCL, POOh. Wait 4 hrs, tag fill @ 3050'. GIH spot 60 sx Class 'C' + 2% CCL, POOH.
4/12/00GIH tag cmt @ 2825' POOH. GIH W/ tbg to 1200', pump 25 sx Class 'C' + 2% CCL. Pull up hole to
400', pump 25 sx Class 'C' + 2% CCL, POOH. Wait 4 hrs, tag cmt @ 304', POOH. GIH W/ 1 jt tbg spot 10 sx
cement, pooh. Cut off csg head, install dry hole marker. Rig Down, cut anchors, clean and dress
location. This well plugged & Abandoned on 4/12/00.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _Bill Keathly_ TITLE _Regulatory Specialist_ DATE _7/10/00_

Type or print name _Bill Keathly_   Telephone No. _915-686-6612_

(This space for State use)

APPROVED BY _Johnny Rahinger_ TITLE _____ DATE _____
Conditions of approval, if any:

GWW