Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs. NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-025-05965

5. Indicate Type of Lease

STATE ☐   FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐   Gas Well ☒   Other

2. Name of Operator
Texaco Exploration & Production, Inc.

3. Address of Operator
P. O. Box 3109, Midland, Texas 79705

7. Lease Name or Unit Agreement Name:

Phillips, J.R.

8. Well No.
12

9. Pool name or Wildcat Eumont
Yates 7 RVRS Queen

4. Well Location

Unit Letter __F__ : __2269__ feet from the __North__ line and __2266__ feet from the __West__ line

Section __6__   Township __20S__ Range __37E__   NMPM __Lea__ County

10. Elevation *(Show whether DR, RKB, RT, GR, etc.)*

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2" CIBP @ 2975' (Yates-Queen) Spot 40 Sx plug 2975'-2700' (B-Salt 8 5/8" shoe) WOC Tag
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL
3. Spot 50 Sx plug 1408'-1100', (T-Salt) Bad Csg 1408'-1342' WOC Tag. (*Bad Csg sqz'd & Circ 250 Sx Cmt to Surf 5 1/2" X 8 5/8") 2/26/95
4. Spot 25 Sx plug 400'-200' (13 3/8" shoe) WOC Tag
5. 10 Sx Surf, 10'-Surf. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _J. T. Corbitt_   TITLE _FACILITY ENGR_   DATE _2/28/01_

Type or print name _James T. Corbitt_   Telephone No. _915 688-4438_

(This space for State use)

APPPROVED BY _____   TITLE _____   DATE _10-18-01_

Conditions of approval, if any: