State of New Mexico
Energy ᵔerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT I
P.C. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-06012

Indicate Type of Lease
STATE ☐   FEE ☒

State Oil & Gas Lease No.
014896

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Lease Name or Unit Agreement Name
BERTIE WHITMIRE

Type of Well:
OIL WELL ☒   GAS WELL ☐   OTHER

Name of Operator
ARCH PETROLEUM INC.

Well No.
2

Address of Operator
10 DESTA DRIVE SUITE 420E

Pool name or Wildcat
Eumont Gas

Well Location
Unit Letter **B** : **660** Feet From The **N** Line and **1980** Feet From The **E** Line

8 Section   **20S** Township   **37E** Range   NMPM   **LEA** County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3566 GR

11   Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	
PULL OR ALTER CASING ☐		
OTHER: ☐		

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	
OTHER: ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
MIRU PU. NDWH NU BOP. DMP 8 SX CMT ON CIBP @ 3690'. SET CIBP @ 3250' CAPPED W/ 35' CMT. DETERMINED FREE PT IN 7" CSG @ 3200'. ND BOP. SHOOT OFF CSG @ 3200'. NU BOP. SET CMT STUB PLUG @ 3200'-50 IN & 50 OUT. SET CMT SHOE PLUG @ 2362'-50 IN & 50 OUT. SET 25 SX CMT PLUG @ 2450, & 1400.' DETERMINED FREE PT IN 9 5/8" CSG @ 500'. ND BOP. SHOOT OFF CSG @ 500'. NU BOP. SET CMT STUB PLUG @ 500'-50 IN & 50 OUT. SET 25 SX CMT PLUG @ 350'. SET 10 SX CMT PLUG @ SURFACE (DISPLACE BETWEEN PLUGS W/ 10# BRINE/ 25# GEL PER BBL MUD). ND BOP & RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____   TITLE SUMMER ENGINEER   DATE 07-01-97

TYPE OR PRINT NAME DOUG PARKHURST   TELEPHONE NO. 915-685-1961

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY: .