UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

1. OIL WELL ✓ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P.O. [illegible]

4. LOCATION OF WELL (REPORT LOCATION CLEARLY AND IN ACCORDANCE WITH ANY STATE REQUIREMENTS.)
AT SURFACE: [illegible]
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

5. LEASE
LC-[illegible]

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Skelly Unit Fee

9. WELL NO.
59

10. FIELD OR WILDCAT NAME
Vacuum Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 20, T-17-S, R-35-E

12. COUNTY OR PARISH
Lea

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐		☐
FRACTURE TREAT	☐		☐
SHOOT OR ACIDIZE	☐		☐
REPAIR WELL	☐		☐
PULL OR ALTER CASING	✓		☐
MULTIPLE COMPLETE	☐		☐
ABANDON*	☐		☐
(OTHER)	☐		☐

(Note: Report results of multiple completion on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If proposed work is directional, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

POOH w/ 2 3/8" tbg and pkr at 9267'. Run [illegible] tbg from [illegible]. Repair csg as required using [illegible]. Drill out [illegible] test. Repeat as needed. Run tbg and pkr. Circ pkr fluid. Set pkr at [illegible]. Place on injection.

18. Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

19. I hereby certify that the foregoing is true and correct

SIGNED [illegible] TITLE [illegible] DATE April 8, 1991

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ISSUED [illegible] DATE _____

APPROVED
APR 10 1991
JAMES A. GILLHAM
SUPERVISOR