NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease

State ☐   Fee [X]

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)

7. Unit Agreement Name

1.
OIL WELL [X]   GAS WELL ☐   OTHER-

2. Name of Operator

Marathon Oil Company

3. Address of Operator

P.O. Box 2409 Hobbs, New Mexico 88240

4. Location of Well

UNIT LETTER ___N___ , ___589___ FEET FROM THE ___South___ LINE AND ___2051___ FEET FROM

THE ___West___ LINE, SECTION ___27___ TOWNSHIP ___21S___ RANGE ___37E___ NMPM.

8. Farm or Lease Name

W.S. Marshall "B"

9. Well No.

1

10. Field and Pool, or Wildcat

Drinkard

15. Elevation (Show whether DF, RT, GR, etc.)

KDB 3420'; GL 3405'

12. County

Lea

16.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [X]   PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐   CHANGE PLANS ☐

OTHER _____

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐   ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐   PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER _____   ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Install BOP.

2. Set bridge plug to isolate lower drinkard.

3. Perforate and stimulate upper intervals in drinkard.

4. Test and place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _Ralph Skinner_   TITLE Engineer Technician   DATE July 10, 1975

Orig. Signed By
L. _____ 31

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY: