STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease: State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- WATER SOURCE

7. Unit Agreement Name

2. Name of Operator
SHELL WESTERN E&P INC.

8. Farm or Lease Name
ARGO A

3. Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

9. Well No.
10

4. Location of Well
UNIT LETTER C, 660 FEET FROM THE NORTH LINE AND 1660 FEET FROM THE WEST LINE, SECTION 22 TOWNSHIP 21-S RANGE 37-E NMPM.

10. Field and Pool, or Wildcat
HARE-SAN ANDRES

15. Elevation (Show whether DF, RT, GR, etc.)
3437' DF

12. County
LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐		COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	CHANGE PLANS ☐	CASING TEST AND CEMENT JOB ☐	
OTHER ☐		OTHER PB Wantz Abo & recompleted to SA for wtr source; tst pmp ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-10 to 5-19-88:
POH w/prod equip. Ran CIBP to 7000'. Shear pin pulled out of CIBP when attempting to set. CIBP fell to TD. Ran 2nd BP & set @ 6995'. Capped CIBP w/35' cmt. Set CIBP @ 5400' & capped w/35' cmt. Perf'd San Andres 4013' - 4900' (1 JSPF). Set RBP @ 4992'. Spotted 420 gals 15% HCl-NEA from 4900' to 4380'. Acd perfs 4390' - 4900' w/12,600 gals 15% HCl-NEA + 2500# rock salt. Reset RBP @ 4340'. Acd perfs 4013' - 4329' w/8400 gals 15% HCl-NEA + 750# rock salt. POH w/RBP. Installed prod equip & tandem BHP bombs. Returned well to prod.

6-02-88:
POH w/prod equip & BHP bombs. SI well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG & PERMITTING DATE 6-17-88

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____