Submit 3 Copies to Appropriate District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-10063

5. Indicate Type of Lease STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Lee Stebbins NCT-A

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER Injector

2. Name of Operator
Chevron U.S.A. Inc.

8. Well No.
2

3. Address of Operator
P.O. Box 670, Hobbs, NM 88240

9. Pool name or Wildcat
Penrose Skelly-GB

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line

Section 5 Township 22S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | | | SUBSEQUENT REPORT OF: | | | |
|---|---|---|---|---|---|---|---|
| PERFORM REMEDIAL WORK | ☐ | PLUG AND ABANDON | ☐ | REMEDIAL WORK | ☐ | ALTERING CASING | ☐ |
| TEMPORARILY ABANDON | ☐ | CHANGE PLANS | ☐ | COMMENCE DRILLING OPNS. | ☐ | PLUG AND ABANDONMENT | ☒ |
| PULL OR ALTER CASING | ☐ | | | CASING TEST AND CEMENT JOB | ☐ | | |
| OTHER: | ☐ | | | OTHER: | ☐ | | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RIH W/CHEMICAL CUTTER & CUT TBG @ 30', ND & CHANGE OUT WH, NUBOPE, RIH W/ OS, ENGAGE 2 3/8" IPC TBG, TOH, LD TBG & AD-1 PKR, TIH W/CICR & WS, SET CICR TO 3208', DISPLACE WELL W/ P&A MUD, STING INTO CICR & SQZ PERFS 3707-58 W/100 SXS CLASS C CMT @ 900 PSI, CAP CICR W/5 SX CMT, TOH, LD 2 3/8" TBG, RU WLU & PERFS 5 1/2" CSG & 1150', TIH W/ CICR & SET @ 1100', ATTEMPT TO PUMP INTO PERFS @ 1150' W/ 2500 PSI, NO SUCCESS, CAP CICR W/20SXS CMT, TOH, SET CMT PLUG F 310' TO SURFACE W/50 SX CMT, DIG OUT CELLAR, CUT OFF WELLHEAD, INSTALL DRY HOLE MARKER, CHANGE STATUS TO PLUG & ABANDONED 12-18-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins TITLE Staff Drlg. Engr. DATE 12-20-89

TYPE OR PRINT NAME M.E. Akins TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY R A Sadler TITLE OIL & GAS INSPECTOR DATE JAN 22 1990

CONDITIONS OF APPROVAL, IF ANY: