Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions re-
verse side)

Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.
LC-032100

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
–

1.

OIL WELL [X]   GAS WELL [ ]   OTHER

7. UNIT AGREEMENT NAME
–

2. NAME OF OPERATOR
TEXACO Inc.

8. FARM OR LEASE NAME   NCT-1
C.H. Lockhart Federal

3. ADDRESS OF OPERATOR
P. O. Box 728 – Hobbs, New Mexico 88240

9. WELL NO.
2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Well is located 660' from the North and 660' from the
West line of Section 18, T-22-S, R-38-E, Unit Letter D

10. FIELD AND POOL, OR WILDCAT
Blinebry, Tubb

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 18, T-22-S, R-38-E

14. PERMIT NO.
Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3354' DF

12. COUNTY OR PARISH
Lea

13. STATE
New Mexico

16.
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	[ ]	PULL OR ALTER CASING	[ ]
FRACTURE TREAT	[ ]	MULTIPLE COMPLETE	[ ]
SHOOT OR ACIDIZE	[ ]	ABANDON*	[ ]
REPAIR WELL	[ ]	CHANGE PLANS	[ ]
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	[ ]	REPAIRING WELL	[ ]
FRACTURE TREATMENT	[ ]	ALTERING CASING	[ ]
SHOOTING OR ACIDIZING	[ ]	ABANDONMENT*	[ ]
(Other) Downhole Commingle			[X]

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The following work on subject well has been completed:

1. Pulled rods and pump from Blinebry zone.

2. Pulled both strings tubing.

3. Ran 6016' (199 joints) 2-3/8" tubing.

4. Installed 4' perforated sub in tubing string and install a pump seating nipple
   above perforated sub at 6020'.

5. Ran rods and pump.

6. Place on production.

7. Clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE Assistant District Superintendent

DATE February 19, 1971

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side