

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 2350 W Marland Blvd. Hobbs NM 88240	Telephone No. 432-631-6982
Facility Name Tony Federal # 28	Facility Type Oil Well

Surface Owner Federal	Mineral Owner	API No. 30-015-33000
-----------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter G	Section 19	Township 17S	Range 31E	Feet from the 1750'	North/South Line FNL	Feet from the 2310'	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil and Produced Water	Volume of Release 2 barrels of oil 3 barrels of water	Volume Recovered 0 barrels
Source of Release Flow Line	Date and Hour of Occurrence 7/29/2014	Date and Hour of Discovery 7/29/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeffery Robertson (BLM)	
By Whom? Bruce Baker	Date 7/29/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flow line was being hot oiled and pressured up resulting in a rupture in flow line. The well was shut in and the flow line was repaired.

Describe Area Affected and Cleanup Action Taken.

The release affected 886 square feet of pasture, and an area of overspray of 31,183 square feet of pasture and lease pad. The area was mapped and surface samples collected and sent to a commercial laboratory for analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: *Bruce Baker*

Printed Name: Bruce Baker

Title: Environmental Technician

E-mail Address: larry.baker@apachecorp.com

Date: 8/14/2014

Phone: (432) 631-6982

Approved by Environmental Specialist:

Approval Date: 8/15/2014

Expiration Date: N/A

Conditions of Approval:

Remediation per OCD Rules and  
Guidelines. Submit remediation  
proposal no later than: 9/15/2014

Attached ☐

2RP-2443

\* Attach Additional Sheets If Necessary