From: <u>Bratcher, Mike, EMNRD</u>
To: <u>Patterson, Heather, EMNRD</u>

Subject:FW: OXY-Corral Draw #2 - Remediation PlanDate:Tuesday, September 16, 2014 2:04:01 PMAttachments:Remediation Packet, Corral Draw #2.pdf

From: Cliff P. Brunson [mailto:cbrunson@bbcinternational.com]

Sent: Thursday, August 28, 2014 11:57 AM

To: Bratcher, Mike, EMNRD

Cc: C J Summers; Ken Swinney; Jennifer Gilkey; Kathy Purvis

Subject: OXY-Corral Draw #2 - Remediation Plan

Mike,

This e-mail is to confirm our conversation on August 11, 2014 about the remediation plan for the above referenced site. I have attached the materials that we used in our discussion. As discussed, Oxy will excavate to a depth of 4 feet across the entire leak area outside of the lined battery. In the areas around SP1, SP2, SB1, SP4, SB3, SP7, and SB2, a liner will be placed in the bottom of the excavations. All of these areas are depicted on the attached site diagram. The liner inside the battery will be cleaned as well. Then the site will then be backfilled with clean soil.

If you would please e-mail your concurrence with this remediation plan, it would be greatly appreciated.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS President

BBC International, Inc.

World-Wide Environmental Specialists

Mailing Address: P.O. Box 805

Hobbs, NM 88241-0805 USA

Shipping Address: 1324 W. Marland St. Hobbs, NM 88240 USA Phone: (575) 397-6388

Fax: (575) 397-0397

E-Mail: cbrunson@bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.
