

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 3/9/2015  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. (575)-738-1739
Facility Name: JL Keel B #94	Facility Type: Production

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-28251
-----------------------	-----------------------	----------------------

### LOCATION OF RELEASE

Unit Letter P	Section 8	Township 17S	Range 31E	Feet from the 1309	North/South Line South	Feet from 1299	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-------------------	------------------------	-------------

Latitude: 32.8470 Longitude -103.8916

### NATURE OF RELEASE

Type of Release: Produced Water/Hydrocarbons	Volume of Release Unknown	Volume Recovered Unknown
Source of Release: Flow line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Feb 2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\*

The release was as the result of a flow line failure from freezing temperatures and is located approximately .5 miles west of the well. This release caused an "overspray" of fluids on the pasture on two sides of the lease road (north and south). The affected area on the north side of the road was approximately 150' x 150' and the south side is measured approximately 30'x100'. DFSI was retained to remediate the site.

Describe Area Affected and Cleanup Action Taken: On June 10, 2014 submitted remediation plans to the BLM and NMOCD. Impacted soils were removed and pasture area restored per BLM guidelines. DFSI respectfully request closure of this incident.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <del>Brian Wall</del> E.L. Gonzales		Approved by Environmental Specialist:	
Title: <del>Construction Foreman II</del> Production Supervisor		Approval Date: 3/18/2015	Expiration Date: N/A
E-mail Address: <del>bwall@linenergy.com</del> elgonzales@linenergy.com		Conditions of Approval:	
Date: 03/09/2015 <del>10/13/2014</del> Phone: <del>806-367-0645</del> 505-504-8002		FINAL Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-709