

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Received 7/21/2015

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company: Bridger, LLC	Contact: Rodney Galindo	
Address: 2009 Chenault Drive. Ste. 100	Telephone No. 469-704-9138	
Facility Name: Artesia Yeso CTB	Facility Type: Tank Battery	
Surface Owner: BLM	Mineral Owner: Federal	API No.

**LOCATION OF RELEASE**

Unit Letter	Section 21	Township 17S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude 32.824902 Longitude -104.184114

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release 9bbls	Volume Recovered 7bbls
Source of Release: Truck vent	Date and Hour of Occurrence 7/12/2015 12:00p	Date and Hour of Discovery 7/12/15 12:00p
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Human error while loading a Bridger Logistics, LLC oil truck resulted in the release of approximately 9bbls of crude oil. Talon/LPE was contacted to conduct an emergency response activities. A vacuum truck was immediately dispatched to recover the standing fluid. Approximately 7bbls of crude oil were recovered.

Describe Area Affected and Cleanup Action Taken.\* Talon/LPE mobilized personnel and equipment to conduct emergency remediation of the impacted area on behalf of Bridger Logistics LLC. PID readings and field chloride titrations were utilized to guide the excavation. Confirmation soil samples were taken at 3 locations within the excavated area (see attached site plan) to insure that all of the impacted soil had been removed. Upon receipt of acceptable laboratory results (see attached table and laboratory report) the excavation was immediately backfilled with caliche and contoured to match the surrounding location so as not to further obstruct truck access to the battery. On behalf of Bridger, LLC we Respectfully request that no further actions be required in regards to this incident

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Rodney Galindo/Talon/LPE/Agent</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rodney Galindo		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: West Texas Field Safety Rep		Approval Date: <u>7/27/2015</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>rgalindo@bridgergroup.com</u>		Conditions of Approval: <b>FINAL</b>	
Date: <u>7/21/2015</u> Phone: <u>469-704-9138</u>		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-3154