

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

fAB1432841543

Release Notification and Corrective Action

nMLB1521930490

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company <i>Enterprise Field Services LLC</i>	Contact <i>Dina Ferguson</i>
<i>PO Box 4324, Houston, TX 77210</i>	Telephone No. <i>210-528-3824</i>
Facility Name <i>Pipeline ROW, 30137 Gathering Lateral</i>	Facility Type: <i>Gas Gathering Pipeline</i>
Surface Owner <i>State of New Mexico</i>	Mineral Owner <i>NA - Pipeline</i>
Lease No. <i>NA</i>	

LOCATION OF RELEASE

Unit Letter <i>O</i>	Section <i>13</i>	Township <i>19S</i>	Range <i>28E</i>	Feet from the <i>97</i>	North/South Line <i>South</i>	Feet from the <i>562</i>	East/West Line <i>West</i>	County <i>Eddy</i>
-------------------------	----------------------	------------------------	---------------------	----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: *N 32.65386* Longitude: *W -104.12857*

NATURE OF RELEASE

Type of Release <i>Natural Gas, Pipeline Liquids</i>	Volume of Release: <i>1,257 MCF, 2 BBL Liquids</i>	Volume Recovered: <i>N/A</i>
Source of Release <i>Pipeline Leak.</i>	Date and Hour of Occurrence <i>04/29/2015 @ 10:05 MDT</i>	Date and Hour of Discovery <i>04/29/2015 @ 10:05 MDT</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher - NMOCD District 2</i>	
By Whom? <i>Osman De Leon</i>	Date and Hour <i>04/29/2015 @ 12:43 MDT</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was detected by pumper passing by. Pipeline segment was clamped and blown down, and leaking portion was repaired following standard One-Call.

Describe Area Affected and Cleanup Action Taken.*

Liquid spill occurred within pipeline ROW. Clean-up activities will be carried out in accordance with Enterprise's General release Notification, Response and Remediation Plan according to housekeeping standards. Enterprise will maintain records of sampling results and disposal documentation, and will make available to NMOCD upon request.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor: Accepted as Initial Report only	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>8/7/15</i>	Expiration Date:
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: Remediation per OCD Rules and Guidelines	Attached <input type="checkbox"/>
Date: <i>8-15-2015</i> Phone: <i>713-381-6684</i>		

* Attach Additional Sheets If Necessary

2RP-3191