

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Lost Tank 33 Federal #2 SWD	Facility Type	SWD
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-29330

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	33	21S	31E					Eddy County, NM

Latitude N 32.42870° Longitude W 103.78971°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80 bbls	Volume Recovered	70 bbls
Source of Release	Coupler on well head failed due to vibration and high pressure	Date and Hour of Occurrence	09/03/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/03/2015 @ 5:03 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The steel coupler on the well head failed due to high pressure and vibration causing 80 bbls of produced water to leak onto the ground. A vacuum truck recovered 70 bbls of produced water and the coupler was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 85' x 40' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/25/2015 and approved by Dara Glass of the BLM via email on 12/14/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Casey Summers

Title: NM Environmental Advisor

E-mail Address: Casey.Summers@oxy.com

Date: 2-23-16 Phone: (575) 513-8289

Approved by Environmental Specialist:

Approval Date: 2/29/2016

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3291