

Received 3/4/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1522941536

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Coyote 21 #2	Facility Type	Well

Surface Owner	McDonald/Bradley	Mineral Owner		API No.	30-015-29864
---------------	------------------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	21	24S	29E					Eddy County, NM

Latitude N 32.19845° Longitude W 103.99052°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5 bbls oil, 30 bbls produced water	Volume Recovered	30 bbls
Source of Release	Over pressure on the stuffing box caused the packing to blow out of the well head	Date and Hour of Occurrence	07/23/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD		
By Whom?	Jennifer Gilkey @ BBC International Inc.	Date and Hour	07/24/2015 @ 5:07 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Over pressure on the stuffing box caused the packing to blow out on the well head and spill 5 bbls of oil and 30 bbls of produced water onto the ground. A vacuum truck recovered 30 bbls of fluids and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 85' x 70' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/30/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: <i>MBratcher</i>	
Title: NM Environmental Advisor		Approval Date: 3/7/16	Expiration Date: N/A
E-mail Address: casey_summers@oxy.com		Conditions of Approval: N/A	
Date: 3-2-16	Phone: (575) 513-8289	Attached <input type="checkbox"/>	
		FINAL	

* Attach Additional Sheets If Necessary

2RP-3203