

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Energy Transfer Partners	Contact: Johnnie Bradford
Address: 600 N. Marienfeld St. Ste. 700 Midland, TX 79701	Telephone No. 817-302-9812
Facility Name: California B Pipeline	Facility Type: Pipeline

Surface Owner: BLM	Mineral Owner:	API No.
--------------------	----------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	9	26S	29E					Eddy

Latitude 32.06428 Longitude -103.99685

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 12bbbs	Volume Recovered: 10bbbs
Source of Release: 16" pipeline leak	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 1/11/2015 2:30pm MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Voicemail NMOCD	
By Whom? Rachel Johnson	Date and Hour: 1/12/15 4:00 pm MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 16" steel line leaked due to corrosion. Following discovery of the release the line was shut in and repaired.

Describe Area Affected and Cleanup Action Taken.*
Talon/LPE (Talon) mobilized personnel to conduct a site assessment and begin remediation of the impacted area. Upon approval of a remediation work plan by BLM and NMOCD, Talon began excavating the impacted soil using PID readings and chloride titrations to guide the excavation. Once field readings indicated that all of the impacted material above NMOCD RRAL's was removed confirmation soil samples were obtained. After review of the laboratory data from the confirmation sampling, NMOCD and BLM approved backfill of the site. The site was backfilled and contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Johnnie Bradford</i>	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Approved by Environmental Specialist:	
Title: Sr. Environmental Specialist	Approval Date: 4/1/2016	Expiration Date: N/A
E-mail Address: johnnie.bradford@energytransfer.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/24/2016 <i>03/29/2016</i> Phone: 817-302-9812	FINAL	

* Attach Additional Sheets If Necessary