

From: [Zachary Luikens](#)
To: [Patterson, Heather, EMNRD](#)
Cc: [Tavarez, Ike](#)
Subject: SM Energy - Osage 8 - 2RP 1185
Date: Tuesday, August 23, 2016 10:07:27 AM
Attachments: image001.png
Osage 8 Initial C141.pdf
Osage 8 Final C141.pdf
Osage 8 C115 and MMS OGOR.pdf

Heather,

Please see attached final C-141 for the close out of 2RP-1185. As stated in the final C-141, this loss of oil was incorrectly accounted for as a spill. However, no spill occurred. A valve malfunctioned allowing Holley to pump unaccounted for oil down their pipeline. The lost oil was reported on a C-115 and the MMS OGOR report (also attached).

Please let me know if there is any other additional info you need to close this out.

Thanks,



Zach Luikens

Sr. Facilities Engineer
6301 Holiday Hill Rd, Bldg #1
Midland, TX 79707
(432) 688-3138 (ofc)
(432) 202-2298 (cell)