

From: [Patterson, Heather, EMNRD](#)
To: ["Blair, Yvonne B"](#)
Cc: [Conder, Haskell P](#); [Bratcher, Mike, EMNRD](#); [Crystal EMNRD Weaver \(Crystal.Weaver@state.nm.us\)](#)
Subject: RE: BE-7-4 Loop C141.doc
Date: Thursday, December 01, 2016 1:13:00 PM
Attachments: 1.coa 4003.pdf

RE: DCP * BE 7-4 Loop * fAB1632651796 * 2RP-4003

Yvonne,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4003.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blair, Yvonne B [mailto:YBBlair@dcpmidstream.com]
Sent: Friday, November 18, 2016 7:56 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Conder, Haskell P
Subject: RE: BE-7-4 Loop C141.doc

Heather

I do apologize my computer did not save correctly to PDF. I have corrected. It is BE-7-4 Loop

Yvonne

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Friday, November 18, 2016 7:49 AM
To: Blair, Yvonne B; Bratcher, Mike, EMNRD
Cc: Conder, Haskell P
Subject: RE: BE-7-4 Loop C141.doc

Your email refers it as the BE-7-4 Loop, but the C-141 lists 10100 ext 2 as the facility name. Which name is correct?

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blair, Yvonne B [<mailto:YBBlair@dcpmidstream.com>]
Sent: Friday, November 18, 2016 7:39 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Conder, Haskell P
Subject: BE-7-4 Loop C141.doc

Correction on GPS location:
Heather/Mike

Good evening, attached is a the initial C141 for the Line leak BE-7-4 Loop for your review.

Yvonne Blair
Compliance Coordinator
DCP Midstream
575-361-2406