

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1622831057

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Sundance Federal A CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-20538

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	4	24S	31E					Eddy

Latitude N 32.24799° Longitude W 103.79063°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	0.25 bbl oil, 50 bbls of produced water	Volume Recovered	45 bbls
Source of Release	Lack of alarms caused excess water to be pumped in from another battery causing a tank spill	Date and Hour of Occurrence	08/09/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/09/2016 @ 2:14 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Lack of alarms caused excess water to be pumped in from another battery causing a tank to spill 0.25 bbl of oil and 50 bbls of produced water. A vacuum truck recovered 45 bbls of produced water and the alarms were reset.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 125' x 112' on location inside the berm. Remediation was completed in accordance with the approved remediation plan from Mike Bratcher of NMOCD via email on 09/28/2016 and from Shelly Tucker of the BLM via email on 10/04/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Casey Summers	Approved by Environmental Specialist: 		
Title: NM Environmental Advisor	Approval Date: 1/10/17	Expiration Date: N/A	
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval: N/A FINAL		Attached <input type="checkbox"/>
Date: 12-16-16	Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary

2RP-3930