

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1629841253

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294, Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Federal 23 #007H	Facility Type	Well
Surface Owner	BLM	Mineral Owner	API No. 30-015-39436

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	26	22S	31E					Eddy County, NM

Latitude N 32.36811° Longitude W 103.75084°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 10 bbls produced water	Volume Recovered	0 bbls
Source of Release	Faulty fitting	Date and Hour of Occurrence	10/08/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	10/11/2016 @ 8:31 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A faulty fitting caused a leak of 2 bbls of oil and 10 bbls of produced water. Recovery was unachievable due to shallow leak depth. The fitting was replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 100' x 165' on location around the well head. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/29/2016 and approved by Shelly Tucker via email on 11/21/2016.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Casey Summers		Approved by Environmental Specialist: 			
Title: NM Environmental Advisor		Approval Date: 1/23/17		Expiration Date: N/A	
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval: BLM approval		Attached <input type="checkbox"/>	
Date: 1-11-17		Phone: (575) 513-8289		FINAL	

* Attach Additional Sheets If Necessary

2RP-3950