

Bratcher, Mike, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Wednesday, February 1, 2017 3:19 PM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'; Price, Henryetta
Subject: RDX 21-32 - characterization plan
Attachments: RDX 21-32 - Characterization Plan.pdf

Good afternoon,
Attached is the characterization plan for the RDX 21-32 spill.
Please let me know if you have any questions or suggestions.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Tuesday, January 03, 2017 9:29 AM
To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RE: RDX 21-32 - initial C-141

Oops It would be helpful if I attached it though... ;)

From: Weaver, Crystal, EMNRD
Sent: Tuesday, January 3, 2017 9:26 AM
To: 'Blaney, Karolina' <Karolina.Blaney@wpxenergy.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RE: RDX 21-32 - initial C-141

RE: WPX Energy Inc. * RDX 21-32 * 30-015-40642 * 2RP-4041

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4041.

Thank you,

Crystal Weaver
Environmental Specialist
OCD – Artesia District II

811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]
Sent: Friday, December 16, 2016 2:29 PM
To: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: RDX 21-32 - initial C-141

Attached is the initial C-141 for the RDX 21-31 produced water spill.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Friday, December 09, 2016 3:40 PM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RDX 21-32 spill notification

Good afternoon,

Here is my Friday spill notification:

This morning WPX had a produced water spill at the RDX 21-32 well pad. API 30-015-40642; K-21-26S-30E. The cause of the spill is mechanical failure of the stuffing box. Estimated 12 bbls was spilled at the wellhead. The spill migrated south of the pad onto the lease road and impacted a small area of vegetation west of the road. Approximately 5 bbls of fluids were recovered. The C-141 report will be submitted by 12-28-16. In the meantime, please let me know if you have any questions or concerns.

Thank you and have a great weekend,

Karolina Blaney
Environmental Specialist
WPX Energy
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com