

Bratcher, Mike, EMNRD

From: Price, Henryetta <hprice@blm.gov>
Sent: Monday, February 13, 2017 12:21 PM
To: Christine Alderman
Cc: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD
Subject: Re: Pintail Fed 23 #8 (API 30-015-38657)

Christine,

Also, in the final C141 please update with the amount of area that was affected. The C141 states it was 2ft by 25ft and in the work plan it depicts a larger area.

The location hasn't been downsized at all, so interim reclamation (IR) will need to be addressed within 3 months. I would double check to see if the stockpile topsoil was affected by this release and if it would affect reclamation. Please submit plans for IR within 30 days. Thank you.

Henryetta Price

Environmental Protection Specialist
Bureau Of Land Management
[Hprice@blm.gov](mailto:hprice@blm.gov)
Phone 575-234-5951
Cell 575-706-2780
Fax 575-234-5927

On Mon, Feb 13, 2017 at 9:36 AM, Price, Henryetta <hprice@blm.gov> wrote:
Christine,

I will let NMOCD take the lead on this one since it is close to ground water, they will make the call for approval. Keep me updated with the sample analysis and progress. Thank you.

Henryetta Price

Environmental Protection Specialist
Bureau Of Land Management
[Hprice@blm.gov](mailto:hprice@blm.gov)
Phone 575-234-5951
Cell 575-706-2780
Fax 575-234-5927

On Mon, Feb 13, 2017 at 9:33 AM, Tucker, Shelly <stucker@blm.gov> wrote:
Henryetta Price will be the Authorized Officer for this release.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Mon, Nov 21, 2016 at 9:54 AM, Christine Alderman <calderman@cimarex.com> wrote:
All,

We had a produced water release at the above named lease 11/20/2016.

50 bbls were released and 2 bbls were recovered.

A 2" threaded fitting corroded and failed. The affected area was pasture and was approximately 2' x 25'.

Please see attached C-141.

Thank you.

Christine Alderman

Cimarex Energy Co.

ESH Supervisor - Permian Basin
Midland TX
Cell - 432.853.7059

-----Original Message-----

From: MidlandScanner@cimarex.com [mailto:MidlandScanner@cimarex.com]

Sent: Monday, November 21, 2016 10:45 AM

To: Christine Alderman <calderman@cimarex.com>

Subject: Message from "RNP0026732E6735"

This E-mail was sent from "RNP0026732E6735" (Aficio MP C5501).

Scan Date: 11.21.2016 10:45:07 (-0600)

Queries to: MidlandScanner@cimarex.com