

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	WPX Energy Inc/RKI	Contact	Karolina Blaney
Address	5315 Buena Vista Dr.	Telephone No.	970 589 0743
Facility Name:	RDU 33	Facility Type:	Well Pad
Surface Owner:	Federal	Mineral Owner:	Federal
		API No.	30- 015-40623


### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	22	26S	30E	2310	FSL	2310	FEL	Eddy

Latitude: 32.0269194N Longitude: -103.8674778W

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100 Bbls	Volume Recovered: 100 Bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Load out line	1/12/2017	1/12/2017 – 12:00 hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Crystal Weaver & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 1/13/17– 11:29 hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.*  The spill was caused by human error. A valve on the unloading line was left open which resulted in a 100 bbl spill into lined SPCC containment. The liner had a pinhole on the southeast corner and a small volume (less than 1 bbl) leaked out of the containment. The spill was contained on the well pad and an adjacent access road.		
Describe Area Affected and Cleanup Action Taken.*  The impacted area was mapped with a Trimble and was sampled for BTEX, TPH, and chlorides in accordance with NM OCD Guidelines for Remediation of Leaks, Spills, and Releases. Please see the attached report.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Karolina Blaney	Approved by Environmental Specialist:	
Title: Environmental Specialist	Approval Date:	Expiration Date:
E-mail Address: Karolina.blaney@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/20/2017	Phone: 970-589-0743	

\* Attach Additional Sheets If Necessary