

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1701247972

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA WTP LP	Contact	CASEY L SUMMERS
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-513-8289
Facility Name	BIG WALT CTB	Facility Type	BATTERY
Surface Owner	STATE	Mineral Owner	STATE
		API No.	30-015-33442

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	2	22S	24E	2006	NORTH	703	EAST	EDDY

Latitude\_N 32.42237\_ Longitude\_W -104.46065\_ NAD83

#### NATURE OF RELEASE

Type of Release	OIL	Volume of Release	10 bbls	Volume Recovered	8 bbls
Source of Release	Tank spill due to battery PLC failure	Date and Hour of Occurrence	12-19-2016	Date and Hour of Discovery	12-19-2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER-NMOCD; CRYSTAL WEAVER-NMOCD		
By Whom?	KATHY PURVIS @ BBC INTERNATIONAL	Date and Hour	12/20/2016 @ 2:42 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Battery PLC failure caused a tank to spill 10 bbls of oil on location inside the berm. A vacuum truck recovered 8 bbls of oil and the PLC was restored to service.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 95' x 135' on location inside the berm. Remediation was completed in accordance with the remediation plan approved for the release (2RP-4069) by Mike Bratcher of NMOCD via email on 2-15-2017.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: CASEY L SUMMERS		Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL ADVISOR		Approval Date: 5/10/17	Expiration Date: N/A
E-mail Address: casey_summers@oxy.com		Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>
Date: 5-4-17 Phone: 575-513-8289			

\* Attach Additional Sheets If Necessary

2RP-4069