District I 1625 N. French Dr., Hobbs, NM 88240 District II District III

1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action

				OPERATOR			Initia	al Report		Fin	al Report			
Name of Co	mpany: L	inn Energy		Contact: Joe	Hernandez			_			_			
Address: 21	30 W Ben	der Blvd I		Telephone No.: 575-942-8675										
Facility Nar	ne: Max F	riess "MA" '		Facility Type: Oil and Produced Water Tank Battery										
Surface Ow	ner: State	of NM)wner:	: BLM			Lease No.: LC-065014							
				•	N OF RELEASE									
II	C4:	Т	D	Feet from the		N OF REI	Feet from the	E4/X	74 T :	Ct				
Unit Letter	Unit Letter Section 30 Township Range 31E Feet from the North					South Line Feet from the Eas		East/ W	Vest Line	County Eddy				
Latitude: 32.808228 Longitude: -103.905249														
NATURE OF RELEASE														
Type of Rele	ase: Oil/Pro	Volume of Release: 25/3 bbl Volume Recovered: 25												
Source of Release: Heater Treated							Date and Hour of Occurrence: 09/09/11 - 1500			Date and Hour of Discovery: 09/09/11 - 1515				
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?								
D W/h 9 F) D-44	-												
By Whom? I Was a Water		ched?	Date and Hour: 09/09/11 - 1600 If YES, Volume Impacting the Watercourse.											
Yes ⊠ No						1 225, Forante Impacting the Franciscourse.								
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	k.										
Describe Cause of Problem and Remedial Action Taken.*: Heater treater over-pressured casing pop-off valve on the top of the unit and the pressure relief valve on the bottom of the unit to open. Describe Area Affected and Cleanup Action Taken.*: Overspray from the top of the unit impacted an area ~ 50' x 90' on the pad. Hydrocarbons from the pressure relief valve flowed outside of the south side of the containment moving westward. The impacted area on the south side is approximately 180' long by 10-15' wide. Vertical impact ranges from 3-6". Corrective action plan attached.														
regulations a public health should their or or the environ	Il operators or the envi operations h nment. In a	are required to ronment. The nave failed to a	o report and acceptant adequately OCD accep	e is true and comp nd/or file certain r ce of a C-141 report investigate and r otance of a C-141	elease r ort by th emedia	notifications and ne NMOCD mate contaminati	nd perform correct arked as "Final R on that pose a thr	ctive acti deport" de reat to gr	ons for rele oes not reli ound water	eases which ieve the ope r, surface wa	may e rator o ater, hu	ndan f liab man	ger oility health	
	1	OIL CONSERVATION DIVISION												
Signature: As Acousty														
Printed Name	e: Jose Herr	nandez	Approved by District Supervisor:											
Title: Foreman						Approval Date:			Expiration Date:					
Date: 09/13/11 Phone: 575-738-1739						Conditions of Approval:				Attached				
* Attach Addi	tional She	ets If Necess	ary											