

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Received 7/18/2017  
NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1704368889

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Matador Resources Company	Contact Catherine Green
Address 500 N Main St Ste One Roswell NM 88201	Telephone No. 575-623-6601
Facility Name Paul 25 24S 28E RB #221H	Facility Type Oil

Surface Owner Fee	Mineral Owner Fee	API No. 30-015-43018
-------------------	-------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter D	Section 25	Township 24S	Range 28E	Feet from the 359	North/South Line N	Feet from the 217	East/West Line W	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude 32.194817 Longitude 104.0487226

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release ~100BBLs	Volume Recovered 80BBLs
Source of Release pipeline	Date and Hour of Occurrence Feb 3, 2017 7am	Date and Hour of Discovery Feb 3, 2017 7:30am
Was Immediate Notice Given? Required x <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Crystal Weaver, voicemail	
By Whom? Catherine Green	Date and Hour Feb. 3 2017 12:07pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes x <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Water recycling facility at Tiger was on Emergency Shut Down. Lease operator went to Paul location that sends water to Tiger. Found that separator Shut Down Valve had failed to close. Lease operator drove right of way to Tiger and found produced water on ground at (~32°11'52", 104°2'55".179999). Well shut in to isolate line, vacuum truck called. Excavator dug down at spill sight, located pipe with hole in it. Crew replaced section of pipe. Excavated area currently fenced off. Vacuum truck removed 80 barrels of produced water. Replaced Shut Down Valve on separator.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 1,165 square yards of surface impacted. Remove and replace impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Catherine Green</u> 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <u>Catherine Green</u> <u>CASEY SNOW</u>		Approved by Environmental Specialist: 	
Title: <u>Regulatory Analyst</u> <u>MONAGLE RES</u>		Approval Date: <u>10/12/17</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>cgreen@matadorresources.com</u>		Conditions of Approval: <u>N/A</u>	
Date: <u>Feb 6, 2017</u> <u>7-18-17</u> Phone: <u>575-627-2453</u> <u>972.371.5439</u>		Attached <input type="checkbox"/>	
FINAL			

\* Attach Additional Sheets If Necessary

2RP-4113