

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1716429454

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC [229137]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GLACIER FEDERAL COM #001H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-43131
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 24	Township 26S	Range 25E	Feet from the 330	North/South Line North	Feet from the 560	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.034333 Longitude -104.342516

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 36 bbls Oil	Volume Recovered: 35 bbls Oil
Source of Release: Tank	Date and Hour of Occurrence: June 8, 2017 9:30PM	Date and Hour of Discovery: June 8, 2017 9:30PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mrs. Weaver-NMOCD & Ms. Tucker- BLM	
By Whom? Aaron Lieb	Date and Hour: June 9, 2017 Time of this E-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A fill line valve was not properly sealed closed for tank sales. It was sealed open, which allowed oil to stay producing into the full tank, which caused tank to overflow.

Describe Area Affected and Cleanup Action Taken.

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator	Approval Date: 10/13/17	Expiration Date: N/A
E-mail Address: rhaskell@concho.com	Conditions of Approval: Like approval BLM	Attached <input type="checkbox"/>
Date: September 21, 2017 Phone: 575-748-1553	FINAL	

* Attach Additional Sheets If Necessary

2RP-4244