Bratcher, Mike, EMNRD

From: Emily Sirgo <emily@mogc-kec.com>
Sent: Tuesday, May 2, 2017 12:46 PM
Tour Shall the Protector Miles FMNR

To: 'Tucker, Shelly'; Bratcher, Mike, EMNRD

Cc: Weaver, Crystal, EMNRD

Subject: Maverick Operating, LLC - PLU 36

Attachments: PLU 36 SITE DIAGRAM.PDF; PLU 36 LAB REPORT.PDF; poker lake 36 c141.pdf

Shelly/Mike- attached is the original C-141, electronic lab results & site diagram which was handled by David Adkins at Talon LPE. Please let me know what it is I need to do next and what kind of data you need. I am not familiar with this type of remediation or the process of reporting.

Thanks

Emily C. Sirgo

Maverick Oil & Gas Corporation

1004 North Big Spring Street, Suite 121 Midland, Texas 79701 432-682-2500 (o) 432-570-1062 (f)

From: Tucker, Shelly [mailto:stucker@blm.gov]

Sent: Tuesday, May 02, 2017 12:50 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>

Cc: Emily Sirgo <emily@mogc-kec.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: Re: Maverick Operating, LLC - PLU 36

Emily,

This release occurred on federal surface. Please ensure the BLM is copied on all correspondence regarding this release. You will also need to obtain authorization from us before commencing with remedial activities.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly G Tucker

Environmental Protection Specialist O&G Spill/Release Coordinator

Bureau of Land Management 620 E. Greene St Carlsbad, NM 88220

575.234.5905 - Direct 575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The <u>BLM acceptance/approval does not</u> relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

<u>Confidentiality Warning:</u> This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, May 2, 2017 at 10:58 AM, Bratcher, Mike, EMNRD < mike.bratcher@state.nm.us > wrote:
RE: Maverick Operating * Poker Lake UT 36 * 2RP-4136 * DOR: Discovered 2/26/17
Emily,
I have received the analytical data for the PLU 36, but I do need an electronic version of it also. Based on the data, OCD will require additional chloride delineation at all sample points except S4.
If you have any questions, let me know.
Mike Bratcher
NMOCD District 2
811 South First Street
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

From: Emily Sirgo [mailto:emily@mogc-kec.com]

Sent: Thursday, April 27, 2017 2:00 PM

To: Bratcher, Mike, EMNRD < <u>mike.bratcher@state.nm.us</u>> **Subject:** Maverick Operating, LLC - PLU 36

Hi Mike,

I sent in the requested info from you after hiring a third party environmental company for the poker lake 36 that should be coming in to your district office. Please advise me what I need to do after you have received. Is there anything else that you are missing from us at Maverick Operating?

Thanks,

Emily C. Sirgo

Maverick Oil & Gas Corporation

1004 North Big Spring Street, Suite 121

Midland, Texas 79701

432-682-2500 (o)

432-570-1062 (f)