

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1708628146 OPERATOR Initial Report Final Report

Name of Company: COG Operating, LLC (OGRID# 217955)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Diamondback 22 State Com #004H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No.: 30-015-40816
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter C	Section 22	Township 26S	Range 28E	Feet from the 20	North/South Line North	Feet from the 1393	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.035183 Longitude: -104.0792542 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 40bbls	Volume Recovered: 37bbls
Source of Release: Firetube	Date and Hour of Occurrence: 3/21/2017 11:30 am	Date and Hour of Discovery: 3/21/2017 11:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver-NMOCD Amber Groves-NMSLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 3/22/2017 7:32 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The firetube failed on the heater treater. A new firetube was installed in the heater treater.

Describe Area Affected and Cleanup Action Taken.*
The release was contained within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheldon L. Hitchcock</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: HSE Coordinator		Approval Date: 10/24/17	Expiration Date: N/A
E-mail Address: slhitchcock@concho.com		Conditions of Approval: N/A	
Date: 10/12/2017	Phone: 575-746-2010	FINAL	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary