

From: [Weaver, Crystal, EMNRD](#)
To: "Rebecca Haskell"; stucker@blm.gov
Cc: [Bratcher, Mike, EMNRD](#); [Jim Amos \(jamos@blm.gov\)](mailto:jamos@blm.gov)
Subject: RE: (C-141 Initial) West Brushy 8 Federal SWD #001 5/27/17 30-015-31675
Date: Tuesday, June 13, 2017 4:36:00 PM
Attachments: [1. 4240 - COAs and signed C-141 Initial.pdf](#)
[2RP-3353 OCD denial.pdf](#)
[2RP-3353 - BLM request for update.pdf](#)
[2RP-3774 last correspondence \(this also includes mention of 2RP-3353\).pdf](#)
[2RP-4094 OCD approval of work plan.pdf](#)

RE: COG * West Brushy 8 Federal SWD #1 * 30-015-31675 * 2RP-4240

Becky,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4240.

PLEASE NOTE: I was also looking in the files for this site location to see if there were any other remediations that we needed an update on and I came across case number [2RP-3353](#). Could we please get an update on that one. I have attached OCD's last response to COG and I also attached BLM's request on 6/13/16 for an update. Also [2RP-3774](#) which BBC International Inc. was contracted to work has not had an update to us since 3/1/17. BBC International states in the email that attached above that the remediation effort for 2RP-3774 will also incorporate a clean-up of the extent of 2RP-3353. So maybe following up with 2RP-3774 will cover follow up of both of these that I have requested. Also may we please get an update on [2RP-4094](#). I also attached a copy of the last correspondence from OCD which was a work plan approval to BBC International on 4/6/17.

Further Note: There have been 7 spills that have occurred at this site location starting since 2014. Therefore, OCD at this time would like to pose the question to COG regarding whether or not a root cause analysis has been conducted for this site location and if any considerations have been made regarding potentially replacing the poly-flow line (if it is the same one that has had reoccurring issues) or if anything further can be done to also prevent the reoccurring pw tank overflow issue.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Rebecca Haskell [mailto:RHaskell@concho.com]

Sent: Thursday, June 1, 2017 12:26 PM

To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; stucker@blm.gov

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Jim Amos (jamos@blm.gov) <jamos@blm.gov>

Subject: (C-141 Initial) West Brushy 8 Federal SWD #001 5/27/17 30-015-31675

Ms. Weaver / Ms. Tucker,

Please see the attached C-141 for your consideration. Please let me know if you have any questions or concerns.

Thank You,

Becky Haskell

Senior HSE Coordinator

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-818-2372 | Main: 432.683.7443

Cell: 432-556-5130

rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rebecca Haskell

Sent: Saturday, May 27, 2017 8:41 PM

To: Weaver, Crystal, EMNRD; stucker@blm.gov

Cc: Mike Bratcher (Mike.Bratcher@state.nm.us); Jim Amos (jamos@blm.gov)

Subject: (Notification) West Brushy 8 Federal SWD #001 5/27/17 30-015-31675

MS. WEAVER / MS. TUCKER,

COG OPERATING LLC IS REPORTING A RELEASE AT THE WEST BRUSHY 8 FEDERAL SWD #001 (30-015-31675) UNIT A SECTION 08 TOWNSHIP 26S RANGE 29E. THE RELEASE OCCURRED AT APPROXIMATELY 4:00 PM ON 5-27-2017. ESTIMATED RELEASED: APPROX. 30 BBLs PRODUCED WATER. ESTIMATED RECOVERED: UNKNOWN AT THIS TIME.

THE RELEASE WAS DUE TO A HOLE IN THE BOTTOM IN A FITTING IN A FLOWLINE. THE FITTING WAS REPLACED. THIS AREA IS BEING EVALUATED AND A C-14 T WILL BE SUBMITTED. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.