From: Weaver, Crystal, EMNRD

 To:
 "Blaney, Karolina"; "Tucker, Shelly"

 Cc:
 Bratcher, Mike, EMNRD; Raley, Jim

 Subject:
 RE: WPX/RKI RDU 45 - C-141

Date:Wednesday, January 17, 2018 12:57:00 PMAttachments:1. 4519 - COAs and signed C-141 Initial.pdf

RE: WPX \* RDU 45 Well Pad \* 30-015-42018 \* 2RP-4519

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval (COA). The OCD tracking number for this event is 2RP-4519, please refer to this tracking number on any and all submissions sent in to the OCD. Please remit a site characterization plan (see COA document included in attachment) or advise OCD of plan of action by no later than 1/24/18.

Thank you,

## **Crystal Weaver**

Environmental Specialist OCD – Artesia District II 811 S. 1<sup>st</sup> Street Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963 Fax: 575-748-9720

**From:** Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]

Sent: Thursday, December 14, 2017 1:47 PM

To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; 'Tucker, Shelly' <stucker@blm.gov>

**Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Raley, Jim

<James.Raley@wpxenergy.com>
Subject: RE: WPX/RKI RDU 45 - C-141

#### Good afternoon,

Attached is the C-141 report for the RDU 45 spill that occurred on 12/2/17. Please let me know if you have any further questions or comments. Thank you,

# Karolina Blaney Environmental Specialist WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina

**Sent:** Sunday, December 03, 2017 10:37 AM

**To:** Weaver, Crystal, EMNRD < <u>Crystal.Weaver@state.nm.us</u>>; 'Tucker, Shelly' < <u>stucker@blm.gov</u>>

**Cc:** Bratcher, Mike, EMNRD < <u>mike.bratcher@state.nm.us</u>>; Raley, Jim

< iames.raley@wpxenergy.com>

**Subject:** WPX/RKI RDU 45 - initial spill notification

### Good morning,

WPX had a small spill yesterday, 12/2/17, at 9:30 am at the RDU 45 well pad. API # 30-015-42018, M-22-26S-30E. The spill was caused by a failure of a buried flowline. Approximately 5 bbls of produced fluids were spilled on location with 2 bbls recovered. None of the spilled fluids has left the pad. I will submit the C-141 report in the next 14 days but please do not hesitate to contact me if you have any questions.

Thank you and have a great rest of the weekend.

### Karolina Blaney

Environmental Specialist WPX Energy Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com