

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Permian LLC	Contact Callie Karrigan
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name: Southern Comfort 25 36 State X No. 001H	Facility Type Oil and gas production facilities

Surface: Owner: state	Mineral: Owner: state	API No. : 30-015-44332
-----------------------	-----------------------	------------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	25	24S	28E	2490	South	2310	East	Eddy

Latitude 321882.Longitude -104.0400

### NATURE OF RELEASE

Type of Release: Fire	Volume of Release: 5 gallons	Volume Recovered: 2.5 gallons
Source of Release: flare	Date and Hour of Occurrence 01/25/2018 04:00 am	Date and Hour of Discovery 01/25/2018 04:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver – Eddy County	
By Whom? Callie Karrigan	Date and Hour 01/25/2018 09:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
Not applicable.

Describe Cause of Problem and Remedial Action Taken.\*

Flowback Operators were onsite working on well when they observed a small fire by beside the completions flare. The fire was immediately extinguished by the Flowback Operators. Upon further investigation, it was discovered that the line had frozen due to cold temperatures and a small amount of condensate and methanol in the line exited the flare. Flowback Operators are now monitoring condensate levels in the knockouts. Trap drains and additional piping were installed on all temporary flares.

Describe Area Affected and Cleanup Action Taken.\*

The affected area was around the base of the flare in a 5'x10' area. The affected area will be scraped and a confirmation sample will be taken and analyzed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<i>Callie Karrigan</i> Signature:	<b><u>OIL CONSERVATION DIVISION</u></b>		
Printed Name: Callie Karrigan	Approved by Environmental Specialist:		
Title: HES Environmental Professional	Approval Date:	Expiration Date:	
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 4/13/2018 Phone: 405-202-1028(cell) 575-297-0956 (office)			

\* Attach Additional Sheets If Necessary

Post Incident



Post Clean-up

