

REVISED - Corrected Lat/Long

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 7/20/2018

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1816336922

217955

OPERATOR

☒ Initial Report

☐ Final Report

| | |
|--|----------------------------|
| Name of Company: COG Operating, LLC (OGRID #229137) | Contact: Robert McNeill |
| Address: 600 West Illinois Avenue, Midland, TX 79701 | Telephone No. 432-683-7443 |
| Facility Name: Copperhead 31 Federal Com #001H | Facility Type: Flowline |

| | | |
|--------------------|------------------------|----------------------|
| Surface Owner: BLM | Mineral Owner: Federal | API No. 30-015-38532 |
|--------------------|------------------------|----------------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| H | 31 | 26S | 29E | 480 | South | 480 | East | Eddy |

Latitude 32.000323 Longitude -104.016294 NAD83

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release Produced Water | Volume of Release 35 bbl. | Volume Recovered 0 bbl. |
| Source of Release Flowline Rupture | Date and Hour of Occurrence May 27, 2018 7:30am | Date and Hour of Discovery May 27, 2018 7:30am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher – NMOCD Shelley Tucker – BLM | |
| By Whom? Dakota Neel | Date and Hour May 27, 2018 12:52pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a pressure rupture in the poly flowline. The flowline is being replaced.

Describe Area Affected and Cleanup Action Taken.*

The release was in the pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---------------------------------------|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: DeAnn Grant | Approved by Environmental Specialist: | |
| Title: HSE Administrative Assistant | Approval Date: | Expiration Date: |
| E-mail Address: agrant@concho.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: May 29, 2018 Phone: (432) 253-4513 | | |

* Attach Additional Sheets If Necessary

2RP-4796