District I 1625 N. French Dr., Hobbs, NM 88240 District II	State of New Mexico Energy Minerals and Natural Resources Oil Conservation Division			
811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410				
District.IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Francis Dr. Santa Fe. NM 87505			

OCD Rec'd:08/09/18

Form C-141 Revised April 3, 2017

onservation Division South St. Francis Dr. Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 5. 50. 1140	cis Di., Sama	i i e, i i i i i i i i i i i i i i i i i	, 	Sa	anta Fe, NM 875	05				
pAB1717258	1.67		Rele	ease Notific	cation and Co	orrective A	ction			
PADI/1/251	, , , ,				OPERA	FOR	🔲 Initial	Report 🔀	Final Report	
Name of Company					Contact C	Contact CASEY L SUMMERS				
Address PO BOX 4294; HOUSTON, TX 77210					Telephone 1	Telephone No. 575-513-8289				
Facility Name STERLING SILVER 3 FED 6 CTB				Facility Typ	Facility Type BATTERY					
Surface Owner: Federal Mineral Owner: Federal API No. 30-015-27638						538				
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	Cou	unty	
F	3	24S	31E					ED	DY	
			Lati	tude_32.24819	95_Longitude10)3.7667236_N	AD83			
NATURE OF RELEASE										
Type of Rele	ase PRO	DUCED WA	TER		Volume of	Release 25 hb	ls Volume Re	covered 0 b	als	

Type of Release PRODUCED WATER	Volume of Release 25 bbls	Volume Recovered 0 bbls					
Source of Release 3 inch poly line from water transfer pump	Date and Hour of Occurrence 6-15-2017	Date and Hour of Discovery 6-16-2017					
Was Immediate Notice Given?	If YES, To Whom? MIKE BRATCHER-NMOCD; CRYSTAL WEAVER-NMOCD; SHELLY TUCKER-BLM						
By Whom? CASEY L SUMMERS	Date and Hour 6-16-2017 @ 12:47PM						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*							
Describe Cause of Problem and Remedial Action Taken.*							
Spill was caused by a failure in a 3 inch poly line from the water transfer pump. Total volume spill was 25 bbls, with no fluid recovered (sandy area). Line was repaired and returned to service.							
Describe Area Affected and Cleanup Action Taken.*							
The affected area from the spill is 40 by 40 ft (measurements are subject to change with future GPS track). Remediation completed in accordance with a remediation plan approved by the NMOCD and BLM. 2RP-4261							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.							
Signature: Mude Settis	OIL CONSERVATION DIVISION						
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: Maria Pruett						
Title: ENVIRONMENTAL SPECIALIST	Approval Date: 08/09/18	Expiration Date: N/A					
E-mail Address wade_dittrich@oxy.com	Conditions of Approval:	BLM Attached					

Date: 8-977 Phone: 57. * Attach Additional Sheets If Necessary

Phone: 575-390-2828

FINAL

2 R P - 4 2 6 1