

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCD Rec'd: 7/31/18

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OGRID: 6137

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company	Contact Aaron Kidd; Foreman Technical Services	
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371	
Facility Name Burton Flat Deep Unit 44	Facility Type Salt Water Disposal	
Surface Owner Federal	Mineral Owner Federal	API No.30-015-32274

LOCATION OF RELEASE

Unit Letter F	Section 3	Township 21S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude_32.635483 N_ Longitude -104.071270 W_ NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40.63 BBLS	Volume Recovered 30 BBLS
Source of Release Inlet Line	Date and Hour of Occurrence 7/17/2018 @ 9:15 AM MST	Date and Hour of Discovery 7/17/2018 @ 9:15 AM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? ENMRD Mike Bratcher and Maria Pruett BLM Shelly Tucker	
By Whom? Brett Fulks; EHS Professional	Date and Hour OCD and BLM 7/18/2018 @ 3:51 PM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Lease operator discovered a flange on the inlet side of the H-pump had developed a leak. Pumps were shut off and the leak was isolated immediately.		
Describe Area Affected and Cleanup Action Taken.* Water released in containment; scheduled recovery of fluids with Vac truck. (PW: Spilled – 40.63 bbls., Rec. - 30 bbls., Lost - 10 bbls.)		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tamala J. Robison</i>		OIL CONSERVATION DIVISION	
Printed Name: Tamala J. Robison		Approved by Environmental Specialist: <i>Maria Pruett</i>	
Title: Field Admin Support		Approval Date:08/16/18	Expiration Date:N/A
E-mail Address: Tamala.Robison@dv.com		Conditions of Approval: Like approval BLM	Attached <input type="checkbox"/> 2RP-4885
Date: 7/25/2018 Phone: 575-748-3371			

* Attach Additional Sheets If Necessary

A#: pMAP1822839361

I#: nMAP1822839627