

Bratcher, Mike, EMNRD

From: Mann, Ryan <rmann@slo.state.nm.us>
Sent: Wednesday, August 8, 2018 9:39 AM
To: 'Adrian Baker'; Bratcher, Mike, EMNRD; Pruett, Maria, EMNRD; stucker@blm.gov; Naranjo, Mark; jamos@blm.gov
Cc: Ashley Ager; Littrell, Kyle
Subject: RE: Backfill/Closure Request Remuda Basin 32-23-30 State #1H Tank Battery/2RP-4420

NMSLO approves backfill. Was any work conducted to address the overspray in the pasture? It is noted in the introduction that 1,430 sq feet were impacted.

Ryan Mann
Remediation Specialist
Field Operation Division
(575) 392-3697
(505) 699-1989
New Mexico State Land Office
2827 N. Dal Paso Suite 117
Hobbs, NM 88240

From: Adrian Baker [mailto:abaker@ltenv.com]
Sent: Monday, August 6, 2018 3:42 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>; stucker@blm.gov; Naranjo, Mark <MNaranjo@slo.state.nm.us>; jamos@blm.gov
Cc: Ashley Ager <aager@ltenv.com>; Littrell, Kyle <Kyle_Littrell@xtoenergy.com>
Subject: Backfill/Closure Request Remuda Basin 32-23-30 State #1H Tank Battery/2RP-4420

All,

Please find the attached report and closure request documenting remediation conducted at the Remuda Basin 32-23-30 State #1H Tank Battery. The work was conducted to address the recent spill with the RP number of 2RP-4420. XTO is requesting backfill/closure approval from the NMOCD and BLM/SLO.

Please let us know if you have any questions, you can contact myself or Kyle Littrell at XTO.

Thank you

Adrian Baker
Project Geologist



LT Environmental, Inc.
3300 North A Street, Building 1, #103
Midland , Texas 79705
(432) 704-5178 office

(432) 894-5641 cell

(432) 704-5179 fax

www.ltenv.com



Connect with us:

This message and any attached files are privileged, confidential, and intended solely for the use of the addressee. If you have received this by mistake, please let us know by reply e-mail and delete it from your system; you may not copy, disclose, disseminate, use or rely upon its content for any use. E-mail transmissions cannot be guaranteed to be secure, error-free, or free of viruses. The sender and LTE therefore do not accept liability for any of these described issues. The comments and opinions expressed herein are those of the author and not necessarily of LTE. Thank you.

Please consider the environment before printing this e-mail.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>
