

Hamlet, Robert, EMNRD

From: Melodie Sanjari <melodie.sanjari@soudermiller.com>
Sent: Friday, March 8, 2019 10:57 AM
To: Bratcher, Mike, EMNRD; Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD
Cc: John Hurt; Heather Patterson
Subject: [EXT] 24 Hour Release Notification Rustler Breaks Tank Battery

Good Morning All,

Responsible Party:

Matador Resources Company
OGRID: 228937
5400 LBJ Freeway, Suite 1500 Dallas, TX 75240
John Hurt
JHurt@matadorresources.com
972-371-5200

Location:

MATADOR PRODUCTION COMPANY
Rustler Breaks Tank Battery
UL:P S: 10 T24S R27E

API: n/a

Facility Type: Tank Battery

GPS Location: 32.2262234 -104.1372621

Surface Land Owner: Private

Cause of Release: equip. error

Release Material: Produced Water

Pathway: The release occurred inside of a lined containment, small portion overflowed onto pad.

Initial Action: Source was eliminated. Vac Truck was dispatched to recover liquids from within lined containment.

Date of Discovery : 3/7/2019

Estimated surface release area: The only release area outside of lined containment covers 2600 ft2

Estimated Volume loss: Predicted to be over 25 bbls of produced water

Estimated Volume Recovered: Approx. 400 bbls of PW recovered from inside lined containment.

Melodie Sanjari

Staff Scientist



Souder, Miller & Associates

Engineering ♦ Environmental ♦ Surveying
201 S Halagueno Street
Carlsbad, NM 88220
www.soudermiller.com
(574) 370-9782 (cell)
(505) 299-0942 Ext. 2204



Notice of Confidentiality and Privileged Status: This electronic mail message, including all attachments, is for the sole use of the intended recipient(s) and may contain confidential and/or privileged information or otherwise may be protected from disclosure. Any unauthorized review, use, disclosure, distribution or actions which rely on the contents of this information is prohibited. If you are not the intended recipient, please contact the sender and delete the message and any attachment(s) from your system.

Statement on Viruses and Harmful Software: While the message and attachment(s) have been scanned with anti-virus software, SMA does not guarantee that this message or any attachment(s) is free of computer viruses or other harmful software. SMA does not accept liability for any damages caused by any computer virus or other harmful software transmitted herewith.